

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number K55007246848	2. Page 1 of 1	3. Emergency Response Phone (800) 483-3718	4. Manifest Tracking Number 008037599 FLE		
5. Generator's Name and Mailing Address Clean Harbors Lone Mountain LLC 2549 North New York Street Wichita, KS 67219 (316) 269-7400		Generator's Site Address (if different than mailing address) SAME					
6. Transporter 1 Company Name US Bulk Transportation Inc		U.S. EPA ID Number PA0987347515					
7. Transporter 2 Company Name		U.S. EPA ID Number					
8. Designated Facility Name and Site Address Clean Harbors Lone Mountain LLC 40305 S County Road 236 Wannoka, OK 73090 (800) 997-3500		U.S. EPA ID Number OKD065438376					
Facility's Phone:							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
			No.	Type			
	1.	HAZ077, HAZARDOUS WASTE, SOLID, N.O.S., (F001, F003), 9, PG III	1	DT	EST 16		F001 F002 F003 F004 F005
	2.						
	3.						
14. Special Handling Instructions and Additional Information 1. CH801502X05 ERGE171 TR# 331 TL# 350A							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offor's Printed/Typed Name Jim Tyson							
Signature Jim Tyson							
Month Day Year 2 3 15							
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:						
	Transporter signature (for exports only):						
	17. Transporter Acknowledgment of Receipt of Materials						
	Transporter 1 Printed/Typed Name K. Rogers						
DESIGNATED FACILITY	Signature K. Rogers						
	Month Day Year 2 3 15						
	Transporter 2 Printed/Typed Name						
	Signature						
18. Discrepancy							
18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection							
Manifest Reference Number:							
18b. Alternate Facility (or Generator) U.S. EPA ID Number							
Facility's Phone:							
18c. Signature of Alternate Facility (or Generator)							
Month Day Year							
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)							
1. H132		2.		3.		4.	
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a							
Printed/Typed Name							
Signature							
Month Day Year							

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator ID Number KSD007246846	2. Page 1 of 1	3. Emergency Response Phone (800) 483-3718	4. Manifest Tracking Number 008037599 FLE		
5. Generator's Name and Mailing Address Clean Harbors Kansas LLC 2549 North New York Street Wichita, KS 67219 (316) 269-7400			Generator's Site Address (if different than mailing address) SAME				
6. Transporter 1 Company Name US Bulk Transportation Inc			U.S. EPA ID Number PAD 987347515				
7. Transporter 2 Company Name			U.S. EPA ID Number				
8. Designated Facility Name and Site Address Clean Harbors Lone Mountain LLC 40355 S County Road 236 Wannoka, OK 73880 (580) 697-3500			U.S. EPA ID Number OKD065438376				
Facility's Phone:							
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))	10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes
			No.	Type			
	X	1. HA3077, HAZARDOUS WASTE, SOLID, N.O.S., (F001, F003), 9, PG III	1	DT	EST 16	Y	F001 F002 F003 F004 F005
		2.					
		3.					
		4.					
14. Special Handling Instructions and Additional Information 1 CH831502X05 ERG171 TR# 331 TL# 350A							
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.							
Generator's/Offor's Printed/Typed Name Jim Tyson							
Signature <i>Jim Tyson</i>							
Month Day Year 2 3 15							
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:						
	Transporter signature (for exports only):						
	17. Transporter Acknowledgment of Receipt of Materials						
	Transporter 1 Printed/Typed Name K. ROGERS						
	Signature <i>K. Rogers</i>						
	Month Day Year 2 3 15						
	Transporter 2 Printed/Typed Name						
	Signature						
	Month Day Year						
DESIGNATED FACILITY	18. Discrepancy						
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection						
	Manifest Reference Number:						
	18b. Alternate Facility (or Generator) U.S. EPA ID Number						
	Facility's Phone:						
	18c. Signature of Alternate Facility (or Generator)						
	Month Day Year						
	19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)						
	1. H132	2.	3.	4.			
	20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a						
	Printed/Typed Name Handy						
	Signature <i>Handy</i>						
	Month Day Year 12 1 15						